



Broken Hill Mine

Broken Hill, New South Wales, Australia

TECHNICAL REPORT

January 1, 2008

Prepared by:

John Sims, a Qualified Person under NI 43-101, Member AIPG (P. Geo.), Director of Mineral Resources, Coeur d'Alene Mines Corporation.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
1.0 SUMMARY	9
1.1. Accessibility, Climate, Local Resources, Infrastructure and Physiography ..	9
1.2. History	10
1.3. Geologic Setting, Deposit Type and Mineralization	10
1.4. Drilling	11
1.5. Mineral Resource and Mineral Reserve Estimation	11
1.6. Mine Operations	12
1.7. Economic ANALYSIS	13
2.0 INTRODUCTION	14
3.0 RELIANCE ON OTHER EXPERTS	14
4.0 PROPERTY DESCRIPTION AND LOCATION	15
4.1. Mineral Tenure	15
4.2. Permits	17
4.2.1. Permits	17
4.2.2. Environmental Issues	19
5.0 ACCESSIBILITY, CLIMATE, LOCAL RESOURCES, INFRASTRUCTURE AND PHYSIOGRAPHY	19
6.0 HISTORY	20
7.0 GEOLOGICAL SETTING	22
7.1. Regional Geology	22
7.2. Broken Hill District Geology	25
8.0 DEPOSIT TYPES	26
8.1. Southern Operations	26
9.0 MINERALIZATION	30
10.0 EXPLORATION	31
11.0 DRILLING	32
12.0 SAMPLING METHOD AND APPROACH	34
13.0 SAMPLE PREPARATION, ANALYSIS AND SECURITY	36
13.1. Sample Preparation Procedures	36
13.2. Sample Analysis	36
13.3. Assay Quality Assurance / Quality control (QA/QC)	37
13.3.1. Standards	38
13.4. Sample Security (Chain of Custody)	59
14.0 DATA VERIFICATION	60
14.1. Down-Hole Survey Data	60
14.2. Database Security	61
14.3. Verification of Drill Hole Intercepts with Geologic Interpretations	61
14.4. Data Entry Verification	61
15.0 ADJACENT PROPERTIES	62
16.0 MINERAL PROCESSING AND METALLURGICAL TESTING	62
16.1. Past and Current Metallurgical Performance	63
16.2. Future Metallurgical Projections	64
17.0 MINERAL RESOURCE AND MINERAL RESERVE ESTIMATES	65
17.1. Mineral Resource Estimation Methodology	65
17.1.1. Data	65
17.1.2. Block Model Estimation Methodology	72

17.1.3.	Block Model vs. Composite Statistics	81
17.1.4.	Resource Classification.....	81
17.2.	Mineral Reserves	87
17.3.	Statement of Mineral Reserves and Resources	88
17.3.1.	Mineral Reserves	88
17.3.2.	Mineral Resources	89
18.0	OTHER RELEVANT DATA AND INFORMATION	95
19.0	INTREPRETATIONS AND CONCLUSIONS.....	96
20.0	RECOMMENDATIONS.....	97
21.0	REFERENCES	98
22.0	ADDITIONAL REQUIREMENTS FOR TECHNICAL REPORTS ON PRODUCTION AND DEVELOPMENT PROPERTIES	99
22.1.	Mining Operations	99
22.1.1.	Pre-Perilya Operations	99
22.1.2.	Perilya Operations.....	99
22.1.3.	Mine Development.....	102
22.1.4.	Production Stoping.....	103
22.1.5.	Backfilling.....	104
22.2.	Processing	104
22.2.1.	Crushing and Grinding.....	105
22.2.2.	Flotation	106
22.2.3.	Concentrate Handling	106
22.2.4.	Tailings Disposal	107
22.2.5.	Mill Production Forecast.....	107
22.3.	Markets	107
22.4.	Contracts	108
22.5.	Environmental Considerations.....	108
22.5.1.	Reclamation	108
22.5.2.	Process Tailings Disposal	109
22.5.3.	Mine Waste Rock Placement	111
22.5.4.	Air Pollution.....	114
22.5.5.	Waste Management.....	115
22.5.6.	Water Management.....	116
22.5.7.	Hazardous Materials Management	120
22.6.	Taxes	120
22.7.	Capital and Operating Costs	121
22.7.1.	Capital Costs	121
22.7.2.	Operating Costs.....	122
22.8.	Economic Analysis	123
23.0	DATE AND SIGNATURE PAGE	125
24.0	CERTIFICATES OF QUALIFIED PERSONS.....	126
	GLOSSARY	128
25.0	APPENDIX.....	129

FIGURES

<u>FIGURE#</u>	<u>PAGE</u>
FIGURE 1-1 LOCATION OF BROKEN HILL, NEW SOUTH WALES	9
FIGURE 4-1 OUTLINE OF PERILYA'S MINING LEASES AT BROKEN HILL, NSW.....	16
FIGURE 4-2 LONGITUDINAL SECTION OF THE BROKEN HILL DISTRICT, NSW.....	17
FIGURE 7-1 STRATIGRAPHY OF THE ROCKS IN THE BROKEN HILL DISTRICT. ORE HOSTS ARE THE PROTEROZOIC-AGED WILLYAMA SUPERGROUP ROCKS. RED SHAPES () INDICATE RELATIVE BASE METAL AND SILVER ORE ABUNDANCE.	23
FIGURE 7-2 GEOLOGIC MAP OF BROKEN HILL DISTRICT AND REGION. THE DEPOSITS OF THE MAIN BROKEN HILL AREA AND POTOSI AREA ARE SHOWN.....	24
FIGURE 7-3 SURFACE GEOLOGY OF THE BROKEN HILL DISTRICT.....	25
FIGURE 8-1 CURRENT AND ORIGINAL CONFIGURATION OF THE SOUTH ORE LENSES/LODES AT BROKEN	27
FIGURE 8-2 LONGITUDINAL SECTION OF THE NORTH MINE LENSES & PLAN 2005 - 2006.....	29
FIGURE 9-1 CHEMISTRY OF THE PRINCIPAL SULFIDE ZONES.....	30
FIGURE 10-1 LONGITUDINAL SECTION SHOWING EXPLORATION FOCUS IN BROKEN HILL SOUTH MINE.	31
FIGURE 11-1 EXAMPLE OF CORE RECOVERY.....	33
FIGURE 12-1 SAWN CORE	35
FIGURE 13-1 GRAPH OF STANDARD DEVIATION OF LEAD VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARDS PLOTTED AGAINST THE DATE ANALYSED. VALUES WITHIN 2 STD FROM THE MEAN ARE CONSIDERED ACCEPTABLE	39
FIGURE 13-2 GRAPH OF STANDARD DEVIATION OF ZINC VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARDS PLOTTED AGAINST THE DATE ANALYSED. VALUES WITHIN 2 STD FROM THE MEAN ARE CONSIDERED ACCEPTABLE	39
FIGURE 13-3 GRAPH OF STANDARD DEVIATION OF SILVER VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARDS PLOTTED AGAINST THE DATE ANALYSED. VALUES WITHIN 2 STD FROM THE MEAN ARE CONSIDERED ACCEPTABLE.....	40
FIGURE 13-4 GRAPH OF STANDARD DEVIATION OF LEAD VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 5 PLOTTED AGAINST THE DATE ANALYSED. VALUES WITHIN 2 STD FROM THE MEAN ARE CONSIDERED ACCEPTABLE	40
FIGURE 13-5 GRAPH OF STANDARD DEVIATION OF ZINC VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 5 PLOTTED AGAINST THE DATE ANALYSED. VALUES WITHIN 2 STD FROM THE MEAN ARE CONSIDERED ACCEPTABLE	41
FIGURE 13-6 GRAPH OF STANDARD DEVIATION OF SILVER VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 5 PLOTTED AGAINST THE DATE ANALYSED. VALUES WITHIN 2 STD FROM THE MEAN ARE CONSIDERED ACCEPTABLE.....	41

FIGURE 13-7 GRAPH OF STANDARD DEVIATION OF LEAD VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 9 PLOTTED AGAINST THE DATE ANALYSED.....	42
FIGURE 13-8 GRAPH OF STANDARD DEVIATION OF ZINC VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 9 PLOTTED AGAINST THE DATE ANALYSED.....	42
FIGURE 13-9 GRAPH OF STANDARD DEVIATION OF SILVER VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 9 PLOTTED AGAINST THE DATE ANALYSED	43
FIGURE 13-10 GRAPH OF STANDARD DEVIATION OF LEAD VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 14 PLOTTED AGAINST THE DATE ANALYSED.....	43
FIGURE 13-11 GRAPH OF STANDARD DEVIATION OF ZINC VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 14 PLOTTED AGAINST THE DATE ANALYSED.....	44
FIGURE 13-12 GRAPH OF STANDARD DEVIATION OF SILVER VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 14 PLOTTED AGAINST THE DATE ANALYSED.	44
FIGURE 13-13 GRAPH OF STANDARD DEVIATION OF LEAD VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 16 PLOTTED AGAINST THE DATE ANALYSED.....	45
FIGURE 13-14 GRAPH OF STANDARD DEVIATION OF ZINC VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 16 PLOTTED AGAINST THE DATE ANALYSED.....	45
FIGURE 13-15 GRAPH OF STANDARD DEVIATION OF SILVER VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 16 PLOTTED AGAINST THE DATE ANALYSED.	46
FIGURE 13-16 GRAPH OF STANDARD DEVIATION OF LEAD VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 18 PLOTTED AGAINST THE DATE ANALYSED.....	46
FIGURE 13-17 GRAPH OF STANDARD DEVIATION OF ZINC VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 18 PLOTTED AGAINST THE DATE ANALYSED.....	47
FIGURE 13-18 GRAPH OF STANDARD DEVIATION OF SILVER VALUES FROM THE MEAN FOR QUALITY ASSURANCE STANDARD 18 PLOTTED AGAINST THE DATE ANALYSED.	47
FIGURE 13-19 HISTOGRAM OF RESIDUAL VALUES (ANALYSED VALUE-STANDARD MEAN) FOR LEAD.	48
FIGURE 13-20 HISTOGRAM OF RESIDUAL VALUES (ANALYZED VALUE-STANDARD MEAN) FOR SILVER USING A DATA SET OF 443 RESULTS.	48
FIGURE 13-21 HISTOGRAM OF RESIDUAL VALUES (ANALYSED VALUE-STANDARD MEAN) FOR ZINC.....	49
FIGURE 13-22 THE GRAPH OF LEAD (PB%) ASSAYS FOR BLANK SAMPLES SUBMITTED AGAINST TIME. VALUES UP TO 0.1% ARE CONSIDERED ACCEPTABLE.....	50
FIGURE 13-23 THE GRAPH OF ZINC (ZN%) ASSAYS FOR BLANK SAMPLES SUBMITTED AGAINST TIME. VALUES UP TO 0.1% ARE CONSIDERED ACCEPTABLE.....	50